## **Innovative Clamping Systems**

- MANUFACTURING
   DEVELOPMENT
- RESEARCH MEASURING TECHNOLOGY



main catalogue **2017** E 08







## Witte Barskamp

Witte was founded in 1969 and initially manufactured complex, highprecision parts for the aerospace industry. Today Witte has developed into a leading manufacturer of fixturing systems and gauges for all kinds of applications. Almost all leading companies from automotive and aircraft industries now rely on Witte technology in order to maintain high quality in their production process.







#### Certification

- Witte Barskamp KG is certified acc. to
- DIN EN ISO 9001
- DIN EN ISO 9100
- QSF-A (Aerospace suppliers)







Introduction Business activities, Vacuum clamping system	2 <sup>ns</sup>
<b>Vacuum supply</b>	6
Liquid separators	20
Vacuum Chucks	22
Witte VAC-MAT <sup>™</sup> ■ Clamping system, Elements	26
Grid Chucks Modular chucks, circular grid chucks	32
Slot Chucks Modular and standard chucks, Starter-Set	40
Microporous Chucks Metapor chucks, standard and special desig	
<ul><li>Perforated grid chucks</li><li>Custom built</li></ul>	60
Vilmill Fleece foil for perforated grid chucks	62
FLIP-POD <sup>™</sup> Vakuum-System ■ Elements, sets	64
Accessories, Replacements	72
Metapor	84
Ice Vice Freeze clamp technology	90
Witte Weiguss	92
Vacuum Base	94
Vacu-Vice	96
Customized clamping solutions Examples	97
Index	.105





## Business activities of Witte Barskamp GmbH & Co. KG

#### Why should you choose Witte Vacuum Systems?

Deciding on Witte systems solutions is a decision for the future and reduces investment for every further project for pumps and fixtures.

Established and proven in many different applications and industries

Full coverage for clamping suitable parts from 10mm<sup>2</sup> to 100mm<sup>2</sup>

All kinds of chuck surfaces (T-slots, slots, macro and micro bores etc.)

Wide range of pumps and units available (Venturi, vane pumps, compressors)

From short term delivery catalogue items to semistandards to complex individual custom-built clamping systems

Continuous new and further developments

No matter what demand and individual application you have, Witte offers you the correct technical and cost-effective solution.



As everything is done under one roof, time consuming interfaces and inevitable cost arising from overlapping are dispensed with.

International sales and service network through own subsidiaries and regional solution partners.

• Experienced project teams with sound knowledge in almost all standards of the automotive industry and their related partners.


#### www - Witte worldwide

We meet the challenges of our customers wherever they occur. Our sales and service network guarantees support worldwide. Witte companies and subsidiaries in Singapore, Mexico and USA as well as long term partners in all major industrial nations ensure the same high service level all over the World.



www - Witte worldwide: www.witte-barskamp.de www.alufix.de www.witteasia.com www.witteamerica.com





# Vacuum clamping systems from Witte

- Machining (milling, turning, drilling, grinding)
- Engraving
- Polishing
- Deburring
- Coating
- Printing
- Irradiation

Vacuum supply for Witte vacuum clamping systems is created using either oil lubricated rotary vane pumps or the proven liquid ring pumps. There are more than 27 variations and sizes available as pumps or units. Venturi valves are obtainable.On turning machines vacuum is catered for via rotating joints directly through the hollow spindle of the machine.Vacuum clamping systems with integrated pumps, tanks, energy modules can be operated completely independently and free


- Measuring (tactile, optical)
- Testing, simulating
- Moving and positioning
- Friction-stir welding
- Laser welding processes
- Visual analysis

from any external supply lines.Complex vacuum fixtures can be equipped with mechanical, pneumatic, hydraulic or electrical clamping, positioning and /or handling units.





## System solutions in detail



Possible material of vacuum chucks

- Steel\*
- Aluminium
- Plastic\*
- Ceramic\*
- Sinterbronze

\*) Available only on request

#### Chuck types

- Grid chuck
- Slot chuck
- Grid hole chuck
- Vac-Mat chuck
- Microporous chuck
- Macroporous chuck
- Flip-Pod chuck
- Grid slot chuck

- Heatable clamping chucks
- Coolable clamping chucks
- Light transmitting clamping chucks



#### **Replacement materials:**

Rubber seal, rubber adapter mat, Vac-Mat™, Foil, Booster, Vilmill™

### System complements



#### Witte IceVice freeze clamping technology:

Witte Weiguß mould clamping technologyldeal for manufacturing of parts, which are almost impossible to clamp conventionally due to lack of suitable clamping surfaces.

> Witte Weiguß mould clamping technology:

Ideal for manufacturing of parts, which are almost impossible to clamp conventionally due to lack of suitable clamping surfaces.







## Vacuum supply, overview



Vacuum units



Modular vacuum units







Vacuum pumps



Liquid ring pumps



# Vacuum Supply

## Pumps Units Workstations

#### Application

We have vacuum pumps available of different types to meet each individual need.

Sizes and capacities vary from 5m<sup>3</sup>/h up to 500m<sup>3</sup>/h and more to guarantee optimal vacuum clamping whatever the circumstances

#### Advantages

- Reliable in continuous operation
- Easy to maintain
- Modular unit has integrated liquid separator
- Space saving assembly for easy access
- Integrated air filter, safety valve
- Witte repair service with spare parts in stock
- Pumps from 5m<sup>3</sup>/h to over 500m<sup>3</sup>/h, also on request dry running pumps
- Liquid ring pumps run on regular machining coolant, pump temperature is regulated by an integrated radiator

#### Handling

- Small light pumps available according to individual need
- Integrated vacuum storage tank
- Different voltages available
- Castors available for mobility in workshop area
- Easy access for emptying liquid separator



### Choosing a vacuum unit or pump

Depending on your operation Witte offers different vacuum supply systems:

#### Handheld pumps / Pumps

are standard, almost all of which can be used together with our liquid separators if fluids are involved and sucked in during machining process page 10

#### Vacuum units

In addition to the pumps mentioned above the vacuum units also have an **additional vacuum tank** as well as various safety devices.

▶ page 12

#### Modular vacuum unit

In addition to the pump and tank the modular vacuum units also have an **integrated liquid separator** and various safety devices

▶ page 16

#### Liquid ring pumps

These pumps are highly recommended when **large amounts of cooling fluids** are sucked in during the machining process

▶ page 14

#### Selection of vacuum supply depending on dimension of clamping surface :

Area	Suction- capacity	Туре	No.
	Capacity		
<1200 cm <sup>2</sup>	5 m³/h	Vacuum pump	99170
<1500 cm <sup>2</sup>	10 m³/h	Vacuum pump	95969
	10 m³/h	Vacuum unit	81010
	10 m³/h	Vacuum unit	81011
	10 m³/h	Modular unit	80172
	10 m <sup>3</sup> /h	Modular unit	80173
<5000 cm <sup>2</sup>	16 m <sup>3</sup> /h	Vacuum pump	82116
	16 m³/h	Modular unit	82146
<1 m <sup>2</sup>	21 m <sup>3</sup> /h	Vacuum pump	80078
	21 m <sup>3</sup> /h	Vacuum unit	80000
	21 m <sup>3</sup> /h	Modular unit	80175
	25 m <sup>3</sup> /h	Liquid ring pump	93801
<2 m <sup>2</sup>	63 m <sup>3</sup> /h	Vacuum pump	80126
	63 m <sup>3</sup> /h	Modular unit, mobile	82150
	65 m <sup>3</sup> /h	Liquid ring pump	93803
<3 m <sup>2</sup>	100 m <sup>3</sup> /h	Vacuum pump	84410
	100 m <sup>3</sup> /h	Liquid ring pump	93804
<4,5 m <sup>2</sup>	160 m <sup>3</sup> /h	Vacuum pump	84412
	160 m <sup>3</sup> /h	Vacuum unit, mobile	84414
	232 m <sup>3</sup> /h	Liquid ring pump	93807
	250 m <sup>3</sup> /h	Vacuum pump	84413
	250 m <sup>3</sup> /h	Vacuum unit, mobile	84208

#### Witte VAC-MAT™

No. of Mats	Required suction capacity
1	3 - 6m³/h
≥ 8	16 - 21 m <sup>3</sup> /h
≥ 20	40 - 63 m <sup>3</sup> /h
≥ 50	100 - 160 m <sup>3</sup> /h

#### FLIP-POD™

Each m<sup>2</sup> of FLIP-POD<sup>™</sup> surface requires 60-100 m<sup>3</sup>/h vacuum suction capacity



## Choosing vacuum supply according to working conditions

Working conditions	Dry machining	Working with fluids
Small clamping area, Small loss of vacuum		& <b>(</b>
Low machining forces	Handheld pump	Handheld pump with liquid separator
Larger clamping area,		&
Higher loss of vacuum,	Vacuum Unit	Vacuum unit with liquid separator
Higher machining forces	Modular vacuum unit	Liquid ring pump
Large clamping area High loss of vacuum High machining forces	Liquid ring pump	Vacuum unit, mobile, with automatic liquid separator
Very large clamping area Very high vacuum loss Very high machining forces	Customized solutions on recurst	Customind colutions on result
	Customized solutions on request	Customized solutions on request

workstations are available with or witout liquid separator





### Vacuum pumps

Oil lubricated vacuum pumps offer the following advantages:

- Air-cooled, therefore do not require coolant
- Highly reliable
- Low operating costs
- Good resistance to condensation
- Integrated oil mist separator, oil filter, check valve on suction side with sieve




### Vacuum pump


220-240 V working voltage, dry lubricated

Nr.	m³/h	Volt	Hz	End press.	Kw	DB	A	В	C	kg
99170	5	230	50	150 mbar	0,14	63	272	153	200	8
288808	15	230	50	120 mbar	0,66	63	412	206	271	29,5
288809	15	400	50	120 mbar	0,55	63	412	206	271	27,5
288810	25	230	50	120 mbar	0,75	65	412	206	271	29
288811	25	400	50	120 mbar	0,75	65	412	206	271	28
288812	40	230	50	120 mbar	1,5	68	484	308	308	40
288813	40	400	50	120 mbar	1,5	68	484	308	308	39
288814	60	400	50	120 mbar	1,5	70	710	363	383	66



99170 Vacuum pump 5m<sup>3</sup>/h











### Vacuum pump

230/400 V working voltage, oil lubricated

Nr.	m³/h	Volt	Hz	End press.	Kw	RPM	DB	Oil	A	В	C	D	Е	F	G	kg
95969	10	230	50	20 mbar	0,37	1350 <sup>1</sup> /min	59	0,31	301	234	297	100	83	150	M8	20,5
281548	10	400	50	20 mbar	0,37	1350 <sup>1</sup> /min	59	0,31	301	234	297	100	83	150	M8	20,5
82115	16	230	50	20 mbar	0,55	2650 <sup>1</sup> /min	60	0,31	301	234	297	100	83	150	M8	19
82116	16	400	50	20 mbar	0,55	2650 <sup>1</sup> /min	60	0,31	301	234	297	100	83	150	M8	19
80156	20	230	50	20 mbar	0,75	2720 <sup>1</sup> /min	62	0,51	401	223	254	131	127	210	M8	22
80078	20	400	50	20 mbar	0,75	2720 <sup>1</sup> /min	62	0,51	401	223	254	131	127	210	M8	22








82115 Vacuum pump 16m³/h

### Vacuum pump

400V working voltage, oil lubricated

Nr.	m³/h	Volt	Hz	End press.	Kw	RPM	DB	Oil	A	В	C	kg
80126	63	400	50	2 mbar	2,0	1500 <sup>1</sup> /min	64	21	640	406	435	62
84410	100	400	50	2 mbar	2,7	1500 ¼min	65	21	699	406	435	80
84412	160	400	50	2 mbar	5,5	1500 ¼min	70	31	920	536	555	150
84413	250	400	50	2 mbar	7,5	1500 <sup>1</sup> /min	72	6,51	1000	581	555	200



Vacuum pump 250m<sup>3</sup>/h



All vacuum pumps can be used with 60 Hz





### Vacuum units

Operating vacuum required can be produced in many ways. Witte vacuum units feature the following:

- Oil lubricated vacuum pumps with an end vacuum rate of 20mbar absolute at full suction capability of i.e. 10 m<sup>3</sup> upto 250 m<sup>3</sup> per hour
- Integrated pressure difference switch, which automatically switches the vacuum pump on or off thereby ensuring vacuum during machining but avoiding unnecessary idle running
- Protection switch which protects electric motor from overheating
- Air filter which protects pump from dirt (made of acrylic glass with exchangeable air filter cartridge)
- Careful assembly of compatible components guarantee trouble-free and almost maintenance-free operation of Witte vacuum units in many applications


- Drainage screw for coolants which have been sucked in
- 3m connecting cable with CEE or Schuko plug




### Witte vacuum unit with U tank

230/400 V working voltage

Nr.	m³/h	Volt	Hz	End press.	Kw	RPM	DB	Oil	Α	В	C	kg
81010	10	230	50	20 mbar	0,37	$1350  \mathrm{M_{min}}$	59	0,31	555	315	327	45
81011	10	400	50	20 mbar	0,37	1350 <sup>1</sup> /min	59	0,31	555	315	327	45
85323	16	230	50	20 mbar	0,55	2650 <sup>1</sup> /min	60	0,31	555	315	327	42
85324	16	400	50	20 mbar	0,55	$2650\ {\rm Imin}$	64	0,31	555	315	327	42
80165	20	230	50	20 mbar	0,75	2720 <sup>1</sup> /min	62	0,51	555	315	327	47
80000	20	400	50	20 mbar	0,75	2720 <sup>1</sup> /min	62	0,51	555	315	327	47
80001	63	400	50	20 mbar	2,0	1500 <sup>1</sup> /min	65	21	800	500	500	105











1 vacuummeter





### Additional vacuum tank

Nr.	Α	В	C	Connection	V	kg
80410	555	315	325	Inner thread G ¾"	541	25,6
80379	800	500	530	Inner thread G <sup>3</sup> ⁄4"	2101	65


• for increasing vacuum storage volume of units


- acts as additional filter and separator for dirt or fluid
- reduces actual running time of vacuum pump





The tank is equipped with two viewing glasses. Dirt and fluid can be seen and drained immediately.











### Maintenance and service kits


Maintenance and service kits for regular care of vacuum units and pumps


For pump/unit with suction capacity	Wear parts kit	Service kit	Gasket kit
10m³/h - 16m³/h	280711	82151	280721
20m <sup>3</sup> /h	280712	80416	280722
63m³/h - 100m³/h	280713	80417	280723
160m³/h	280714	280698	15202
250m³/h	280715	280699	15205
Comprising of:	Wear parts, Gaskets	Filter elements, gaskets, oil	Gaskets

Maintenance and service can be carried out on site with these kits.









- a Liquid ring vacuum pump
- **b** Suction filter
- c Condenser
- d Motor
- e Chiller
- f Fluid reservoir
- g Level indicator
- h Operation selection
- i Drain plug
- k Valve
- m Air release valve
- n Shockproof plug


### Liquid ring vacuum pumps

#### Only one unit for vacuum supply and liquid separation

These robust pumps, are low on wear-and-tear and maintenance, work at up to 50 mbar vacuum and do not need an additional liquid separator.

A fast turning impeller causes water in the pump to rotate (see picture on left) simultaneously sealing itself off the impeller. A washable filter and a patented condenser clean the air being sucked in before it enters the pump. Cooling lubricant is integrated into pump's operating cycle and a valve allows removal of excess fluid which can be returned to tool machine whilst in operation.

An air chiller protects the unit from overheating.







### Liquid ring vacuum pump

	Nr.	m³/h	Volt	End press.	Kw	DB	Hz	Α	В	C	kg
•	93801	25	400	150-50 mbar	0,83	66	50	463	432	602	38
	93802	48	400	150-50 mbar	1,2	70	50	515	572	743	58
	93803	68	400	150-50 mbar	2,4	74	50	515	572	743	71
	93804	105	400	150-50 mbar	3,85	77	50	525	620	920	95
	93805	150	400	150-50 mbar	4	74	50	710	845	1100	188
	93806	198	400	150-50 mbar	5,5	76	50	710	845	1100	198
	93807	232	400	150-50 mbar	7,5	73	50	710	845	1100	275




- Supply includes
   1 pce connection unit comprising:
  - 3m vacuum hose
  - 3/2 way aerated valve
  - 1 vacuummeter









### Liquid ring vacuum pump – Accessories

	Nr.	Description	for pump	Version	ġ
•	13468	Air filter element 3µm, polyester	Type 22	Washable	79
•	13469	Air filter element 3µm, polyester	Туре 45-100	Washable	330
•	13471	Air filter element 3µm, polyester	Type 232	Washable	480
•	13534	Water filter (exchange in pairs)	all	Washable	40



Preference item: Articles with green diamond are available ex stock!

All vacuum pumps can be used with 60 Hz





### Modular vacuum units


#### Advantages:

- Vacuum storage unit and liquid separator are integrated - an additional liquid separatoris not required
- Space saving assembly of all components
- See-through unit for liquid separator and vacuum storage unit all in one means safety "at a glance"
- Different storage volumes possible simply by changing acrylic glass cylinder
- Integrated air filter, drain separator, overvoltage relay, pressure difference switch
- Available with different pump types from 10 m<sup>3</sup> to 100 m<sup>3</sup>, on request also available with dry running pumps





- Supply includes
- 1 pce connection unit comprising:
- 3m vacuum hose
- 3/2 way aerated valve
- 1 vacuummeter



m

ñ υ

### Modular vacuum unit

230/400 V working voltage

	Nr.	m³/h	Volt	Hz	End press.	Kw	RPM	DB	Oil	A	В	C	D	kg
	80172	10	230	50	20 mbar	0,37	$1350 \ \mathrm{Min}$	60	0,31	ø320	360	650	460	32,5
	80173	10	400	50	20 mbar	0,37	$1350 \ {}^1\!\!/_{\text{min}}$	60	0,31	ø320	360	650	460	32,5
•	82147	16	230	50	20 mbar	0,55	2650 <sup>1</sup> /min	60	0,31	ø320	360	620	460	30,5
	82146	16	400	50	20 mbar	0,55	2650 <sup>1</sup> /min	60	0,31	ø320	360	620	460	30,5
<b></b>	80174	20	230	50	20 mbar	0,75	2720 <sup>1</sup> /min	62	0,51	ø320	420	620	460	33,5
	80175	20	400	50	20 mbar	0,75	2720 <sup>1</sup> /min	62	0,51	ø320	420	620	460	33,5







## Modular vacuum unit

400 V working voltage


	Nr.	m³/h	Volt	Hz	End press.	Kw	RPM	DB	Oil	Α	В	C	kg
•	82150	63	400	50	2mbar	2,0	1500 <sup>1</sup> /min	64	21	640	640	1055	118
	83467	100	400	50	2mbar	2,7	$1500 \ \text{min}$	65	21	640	640	1055	132




- Supply includes 1 pce connection unit comprising:
  - 3m vacuum hose
  - 3/2 way aerated valve
  - 1 vacuummeter



83467 Modular vacuum unit, 100m<sup>3</sup>/h





All pumps in modular units have oil lubrication. Dry running vacuum pumps for modular units are available on request



Preference item: Articles with green diamond are available ex stock!

All vacuum pumps can be used with 60 Hz






### Witte vacuum unit

400 V working voltage, mobile

Nr.	m³/h	Volt	Hz	End press.	Kw	RPM	DB	Oil	A	В	C	D	kg
92302	100	400	50	2 mbar	2,7	1500	65	21	1000	800	1274	525	210
84414	160	400	50	2 mbar	5,5	1500	70	51	1000	800	1274	525	337
84208	250	400	50	2 mbar	7,5	1500	72	6,51	1000	800	1274	525	337











### Witte Compact Systems

Vacuum generation for large scale vacuum chucks or multiple operations

For process-safe vacuum clamping on a large scale corresponding powerful vacuum generation is required. These vacuum generators comprise of several vacuum punps connected together and arranged one above the other in a space-saving rack.An integrated controller assumes fully automatic operation of the equipment thereby achieving a high degree ofprocess reliability.Continuous stand-by operation and a large vacuum tank enable set up at a distance from the actual vacuum clamping system.They are particularly well suited as a central power generation system, for example for the supply of complete machine halls and / or several manufacturing centers equipped with vacuum chucks.


The wide range of these central vacuum systemsvaries from 100m<sup>3</sup> / h to more than 1000m<sup>3</sup> / h suction capacity with a maximum ultimate vacuum of up to 0,5 mbar. Versions in special arrangements available on request.











C

ш


Q

Füllhöhe fill to max.

øΑ


В


### Liquid separator, small



### Liquid separator, medium









Preference item: Articles with green diamond are available ex stock!

### Liquid separator, large

Nr.	A	В	Vol./Capacity	Connection	kg
94953	600	645	72/501	LW32	40





### Automatic liquid separator


Nr.	V(I)	l/h	m³/h	LW in	LW out	Α	В	C	D	kg
80155	3,5	100	bis 100	G 1¼"	G 1¼"	685	400	360	175	8,5
82782	9,5	100	160-250	G 2"	G 2"	950	410	340	290	15
288327	20	250	250-800	DN 50	DN 50	830	382	282	-	24.8


Fully automatic operation is guaranteed with an integrated magnetic valve and 2-chamber system. The separator is set up between vacuum chuck and pump, thereby protecting vacuum pump from the large amounts of fluid, which are absorbed and Fluids, which are sucked in, are transported back to the machine by means of a hose system.

Clamping of the workpiece is not interrupted at any time. Electricity supply of 230V is necessary for operation. Also available in 110V/60 Hz version.

We advise using the reducer connections (page 81) and hose nozzles (page 82) suitable for your vacuum hose diameter. Two are required for each part, one in and one out of the automatic liquid separator These parts are not included and need to be ordered separately!








### Stand filter


Nr.	V(I)	l/h	m³/h	LW in	LW out	Α	В	C	D	E	kg
15039	25	100	bis 100	59,6	G 1½"	685	400	360	175	M8	8,5
15285	25	100	160-250	59,6	G 2"	950	410	340	290	M8	15

15039 Filter STF 0250 with fleece insert For separation of fluids and solids out of suction medium incl. quick clean flap and fluid drainage tap

15285 Stand filter STA 250 with automatic fluid separation24 Volt DC














## Vacuum chucks





Microporous chuck







VAC - Mat<sup>™</sup> Sets



Grid vacuum chuck



Slot vacuum chuck



Grid hole vacuum chuck





Microporous vacuum system





### **Clamping with vacuum**






### Setting up a vacuum system




Workpieces with small surfaces



Slot chuck with perforated rubber adapter mat



Witte VAC-MAT™




Chuck with insert made out of sintered metal or Witte Metapor© for foils and skins

#### Vacuum supply:

A modular vacuum unit with integrated liquid separator, storage tank and pressure control. Altogether almost 50 different variations of vacuum pumps and unit are available

#### Vacuum distributor, connection unit or safety appliance:

Distribution of operating vacuum to the chucks. Gauges, choice of manual or magnetic valves and pressure controls for watching over operating vacuum level. All these variations are available.







Chucks

Microporous vacuum system

Vacuum chucks: Chucks to accomodate your requirements and clamping operations.

Vacuum supply from page 6







## Witte VAC-MAT<sup>™</sup>

The vacuum system you can cut right into!

#### Application

Wide spectrum of different workpiece forms can be clamped

- Grinding
- Milling
- Drilling
- Five sided treatment including milling into the Vac-Mat

#### Advantages

- Strong hold down force
- Clamping surface with a high friction value
- Milling through of outer and inner contours
- Precise and exact cut outs due to the fact that the workpiece can be milled through into the VacMat leaving a clean cut edge

#### Handling

- Set up time reduced to seconds as fitting of single rubber seals become obsolete
- Surface friendly material which avoids scratching of workpiece surface area
- No extra clamping fixture needed







### Witte VAC-MAT<sup>™</sup> Application

#### What is VAC-MAT<sup>™</sup> ?

It is a thin soft polymer mat with many spaced out vacuum points, suckers in different sizes with a fine hole in each centre and a raised lip. On the underside there are six lugs which locate in the special VAC-MAT<sup>TM</sup> chuck. On the mat under surface there are grid shaped grooves which distribute the vacuum to each of the small holes. A lip right around the outside edge ensures no leakage.

#### What size is VAC-MAT<sup>™</sup>?

All VAC-MAT<sup>TM</sup>s are 2,5 x 200 x 300 mm. The tolerance lies at +/- 0,04mm and concave upto 0,1mm. To increase the size of the working area, the modular VAC-MAT<sup>TM</sup> chucks are connected to one another and VAC-MAT<sup>TM</sup> s are simply placed on as described.

#### What is the minimum work piece dimension for VAC-MAT™?

Minimum 50% of each mat must be covered by the workpiece.

#### Is VAC-MAT<sup>™</sup> reusable?

The working life of a VAC-MAT<sup>™</sup> depends on the number and size of cuts made into the mat during machining.

#### Operating temperature for VAC-MAT<sup>™</sup>


Vac-Mat<sup>™</sup>, available in RED, BLUE and GREEN versions can be used at 40°C without any limitations




The lugs underneath the mat guarantee fast and accurate positioning of the VAC-MAT<sup>™</sup> on the special modular vacuum chuck



The modular concept allows connection of several vacuum chucks. The vacuum supply to each chuck continues through the connection elements.






In modular chucks additional holes can be drilled in the green areas to allow insertion of pins for positioning. Further information on page 104.








### VAC-MAT™

modular chuck, single

-	Nr.	Pcs	Dim	kg
¢	81759	1	30x200x300	6,4

#### Supply includes:

- 10 VAC-MAT/blue
- Vacuum chuck adapter plate
- Vacuum suction hose 1m incl. connector
- 2 clamps for mounting chuck
- Assembly tool




### 82837 VAC-MAT<sup>™</sup> double

modular chuck, double

	Nr.	Pcs	Dim	kg
82	2837	1	30x300x400	10,8

#### Supply includes:

- 10 VAC-MAT/blue
- Vacuum chuck adapter plate
- Vacuum suction hose 1m incl. connector
- 2 clamps for mounting chuck
- Assembly tool



### 82825 VAC-MAT™

modular chuck, four times

Nr.	Pcs	Dim	kg
82825	1	30x400x600	20

#### Supply includes:


- 10 VAC-MAT/blue
- Vacuum chuck adapter plate
- Vacuum suction hose 1m incl. connector
- 2 clamps for mounting chuck
- Assembly tool



Preference item: Articles with green diamond are available ex stock! Other dimensions on request. Dedicated chucks are also available but Vac-Mats™ are 200x300 mm, any larger surface area must be a multiple of 200x300 mm.















Minimum order quantity 10 pcs per colour

#### Witte VAC-MAT<sup>™</sup>

in different versions


	Nr.	Color	A	В	C	g
$\diamond$	11030	blue, standard	300	200	2,5	102
•	11053	green, hard	300	200	2,5	102
•	11548	red, soft	300	200	2,5	102
\$	11029	<b>black</b> , for covering areas not required during machining	300	200	2,5	102






### Hose connector

incl. O-Ring





# Vacuum chuck adapter incl. 0-Ring

Nr.	А	В	ġ
81762	23	41,6	32







Preference item: Articles with green diamond are available ex stock!








### Sealing






в

### Tool for setting up








### Height adjustable end stops

in form of excentric washers:

Nr.	for height of plate	Α	В	C	D	Pcs	ğ
85405	32,5	20	M5	9	16	6	38
85409	38,0	27	M6	11	20	9	90
85410	48,0	30	M6	12	20	12	132













Custom built tombstone with integrated storage tank, magnetic Valve and 6 pc grid type chucks.

## **Grid chucks**

### Modular version Standard sizes Special design

#### Applications

For simple shaped workpieces with a rough surface and heavy duty milling

- Grinding
- Milling
- Turning

#### Advantages

- Strong hold down force
- For universal applications
- Secure clamping of rough workpiece surfaces due to high friction properties
- The O-shaped seal evens out any irregularities between workpiece and chuck surface

#### Handling

- Any shape or size of chuck made to measure
- Recommended grid size depends on workpiece contour and dimensions
- Clamping area defined by O-shaped seal
- Finely gridded vacuum chucks for extremely small parts
- Ideal as a base for many solutions together with special vacuum adapter plates










Vacuum fixture with cylindrical geometry for clamping aircraft fuselage segments (#94651)

1 1 . F








#### **Grid chucks**

modular type

	Nr.	А	В	C	D	kg
<b></b>	89676	300	200	32,5	12,5	5,6
	90249	400	300	32,5	12,5	10
-	92289	600	400	32,5	12,5	20

#### i Supply includes:

- Modular chuck
- 10m O-shaped seal, ø 4 mm
- Vacuum adapter plate
- Im wire spiral hose
- 2 clamps for mounting chuck
- Assembly tool



The modular concept allows connection of several vacuum chucks. The vacuum supply to each chuck maintained by connecting sleeves.



### **O-shaped seal**



Used for sealing grid chucks or workpiece specific contours. This high quality seal is placed into the slots of a vacuum grid type chuck to define the clamping area.

Minimum order quantity 50m








Witte vacuum chucks are available in other versions and dimensions on request




## **Grid chucks**

standard type, grid 12,5 mm

Nr.	Α	В	C	D	kg
285709	300	200	38	12,5	6,4
80807	400	200	38	12,5	8,5
80808	500	200	48	12,5	19,4
80809	600	200	48	12,5	16,2
80810	400	250	48	12,5	13,5
80811	500	250	48	12,5	16,8
80812	400	300	48	12,5	16,2
80813	500	300	48	12,5	20,2
80814	400	400	48	12,5	21,5
80815	600	300	48	12,5	24,2
80816	600	400	48	12,5	32,3
80817	800	400	48	12,5	43
80818	1000	500	48	12,5	67




## Vac-Mat adapter plate



for Grid chucks







Grid vacuum chuck Starter Sets

Grid vacuum chuck with vacuum supply via Venturi valve

Nr.	А	В	C	kg
282126	300	200	32,5	5,3
282127	400	300	32,5	10,6
282128	600	400	32,5	21,2

#### Supply includes:

- Grid vacuum chuck
- Vacuum supply (Venturi valve integrated in chuck)
- O-shaped seal ø4mm
- pressure hose with plug connection
- 2 clamps for mounting chuck
- Tool for changeover from Venturi valve to vacuum pump

These tried and tested standard grid type vacuum chucks as described on page 34 are made of medium tensile aluminium.

The grid size is 12,5 mm. The height adjustable excentre stops enables fast, accurate positioning of parts and restricts sideways movement

Vacuum supply made easy via compressed air (ISO 8573-1:2010) as operating medium. The integrated vacuum pump (Venturi System) requires operating pressure of 3,5-6 bar. End vacuum is 80mbar absolute (92% vacuum). The chuck has an integrated silencer to reduce noise. Chuck can be used with integrated Venturi valve or with a vacuum pump. Tools for changeover are included.






Preference item: Articles with green diamond are available ex stock!



## Grid chucks – Special design



In addition to standard sizes shown in the catalogue Witte grid type chucks are also custom built to suit your requirements up to dimensions of more than 40m<sup>2</sup>.

Dimensions of chuck and clamping area, grid size, slot width, downforce and best type of clamping surface are all details taken into account to supply a chuck which gives optimal results for the application in question.


Chucks can be made according to a customer's workpiece design drawing, let us help you find the best way to clamp your workpiece.



Customized vacuum chuck for the aircraft industry, similar chucks have also been supplied for the spacecraft industry








3D Vacuum chuck with several movable segments for clamping aircraft fuselage parts during milling and friction stir welding processes

Convex vacuum fixture with a backing along the length for clamping aircraft wing parts during friction-stir welding




Vacuum fixture for clamping aircraft wing parts during friction-stir welding

3D vacuum fixture for fixation of pre-formed aluminium parts. Complex contours are milled and cutouts held securely while under the influence of vacuum downforce.







# **Circular chucks**

# Suitable for circular type workpieces

#### Applications

For simple shaped workpieces with a rough surface and heavy duty milling


- Grinding
- Milling
- Turning

#### Advantages

- Strong hold down force
- For universal applications
- Secure clamping of rough workpiece surfaces due to high friction properties
- The O-shaped seal evens out any irregularities between workpiece and chuck surface

#### Handling

- Any shape or size of chuck made to measure
- Recommended grid size depends on workpiece contour and dimensions
- Clamping area defined by O-shaped seal
- Finely gridded vacuum chucks for extremely small parts
- Ideal as a base for many solutions together with special vacuum adapter plates



## **Circular Grid Vacuum Chucks**

aluminium

Nr.	Grid	Øxh	<b>.2</b>
NI.	GIIU	۶XII	kg
80836	10,0	100 x 38	1
80837	10,0	125 x 38	1
80838	10,0	160 x 38	2
80839	10,0	200 x 38	3
80840	10,0	250 x 38	5
80841	12,5	315 x 48	5
80842	12,5	400 x 48	16
80843	12,5	500 x 58	31
80844	12,5	630 x 58	49









# Slot vacuum chucks

## Standard sizes Adapter mats Custom made chucks

The chuck surfaces feature slots depending on application. For clamping of work pieces, which do not cover the entire surface, rubber adapter mats are required.


#### Applications

For light machining operations such as

- Milling
- Drilling (e.g. printed circuit boards, electronic components)
- Engraving
- Machining of complicated work piece shapes with cutouts etc.

#### **Special advantages**


- Low height
- Wide range of applications through the use of rubber adapter mats
- Ideal for HSC (High Speed Cutting) initial milling together with plane-parallel pre-machined rubber adapter mats
- Clamping very small work pieces is possible



#### Handling

- Simplifies part positioning using height adjustable stop bars
- Defining of active vacuum area using vacuum stopper and rubber adapter mats (Example see picture above)






## **Compact Slot Vacuum Chucks**


	Nr.	В	L	C	kg
•	286641	200	300	38	5,5
•	286642	300	400	38	11,2
•	286643	400	600	38	23

Prepared for Zero Clamp system (Not for No. 286641)





Preference item: Articles with green diamond are available ex stock!



#### ① Supply includes:

- Compact slot chuck
- Adjustable stops on all sides
- 1m hose with connector
- Fitting rubber adapter mat, red
- 2 clamping claws









4 slot chucks on a machine used for manufacturing aluminium carriers. Machining of inner and outer contours is done in one process thanks to rubber adapter mats.



Slot vacuum chuck with three vacuum areas which can be used individually.






## Slot vacuum chuck Starter Set


Slot - Vacuum chuck with Venturi vacuum generator

Nr.	Α	В	C	D	E	F	kg
95167	300	200	32	209	309	30	5,3
284555	400	300	32	409	309	30	10,6
284556	600	400	32	409	609	30	21,2



#### Supply includes:

- 1 Vacuum supply (venturi nozzle)
- 2 Clamps for mounting chuck
- 1 Vacuum stopper
- 1 Rubber adapter mat
- 1 Pressure hose with quick connector for compressed air connection



1. Vacuum generation simply by using compressed air on site: The built-in vacuum pump (Venturi system) requires operating pressure of 4-6 bar.

Ultimate vacuum is is 150mbar absolute (85% vacuum). Air consumption is 30-42 l/min. An integrated silencer reduces the noise of the escaping air.

2. Slot vacuum chuck made of aluminum alloy: In this chuck, vacuum generation is already integrated and ready for immediate use. For work piece positioning there are exentric stops located on two sides of the vacuum chuck. The rubber adapter mat is perforated by user as required and enables clamping of smaller components.


A vacuum stopper defines active vacuum area. The connection is made via a pressure hose and a plug for standard pneumatic connections.

The plates can be operated with the integrated venturi pump or a vacuum pump.






## Slot vacuum chucks and rubber adapter mat





Position workpiece with the help of adjustable end stops. Then draw round the contour using an ordinary pen





Using the slot chuck with the rubber adapter mat allows drilling of holes and milling or cutting of pockets and cutouts into the mat to a depth of 1,5mm without losing vacuum. As the mat suffers hardly any wear and tear it can be used often for workpieces with the same contour.

Certain applications allow the tool to work to depths of 1,5mm into the mat.

Height tolerance of the mats lies in a range of +/- 0,3mm (DIN 7715, part KI. P2)








4

Remove the mat and punch holes into the area corresponding to the actual clamping surface of the workpiece. The holes should be approx. 3-8 mm Dia. in a 10mm grid and lie on slots of the chuck

5

Replace workpiece onto the mat. The excellent friction of the rubber material counteracts high-displacement forces better than any other vacuum system








## Rubber adapter mats

for slot vacuum chucks

	Nr.	Α	В	C	g
<b>♦</b>	00416	200	300	3	226
	00609	200	500	3	378
	00564	200	600	3	453
	00009	300	150	3	170
	00010	350	150	3	200
	00011	400	200	3	300
	00013	350	250	3	330
	00014	300	300	3	340
No. 1	00015	250	400	3	370
♦	00016	400	300	3	460
Rubber adapter mats, brown, for use on slot type vacuum	00017	400	400	3	602
chucks (see also page 40)	00415	500	300	3	560
	00164	500	500	3	941
	00418	500	1000	3	1890
Preference item: Articles with green diamond	00437	600	300	3	678
are available ex stock!	00414	600	400	3	904
	00409	1000	1000	3	3766
Other dimensions available on request	00682	1000	2000	3	7550
	00732	1000	2000	1	2500
	00733	1000	2000	1,5	3980



### Rubber adapter mats

blue


	Nr.	lxw	Thickness	kg
٥	14927	2000 x 400	1	1
	17302	9100 x 400	1	4,5

The blue rubber adapter mat is placed between part and chuck. It covers areas of the chuck not in use and secures part against slipping due to high friction value.

Areas covered by part, must be punched with holes or cut with slits.

Rubber adapter mat - blue. Only available as a complete roll.





**Blue mat** (meterwise from roll): Most accurate product, highest friction, ideal for parts with small clamping areas, reusable

Black mat (cut to order): Can be milled over, low friction, reusable


**Red mat** (cut to order): Cannot be milled over, medium friction, ideal for drilling holes through parts, reusable



## Rubber adapter mats

for slot vacuum chucks

	Nr.	А	В	C	ğ
•	00280	200	300	3	260
	00849	200	500	3	378
	00850	200	600	3	453
	00851	150	300	3	170
	00825	200	400	3	360
	00852	250	350	3	392
	00853	300	300	3	410
	00796	250	400	3	370
•	00854	300	400	3	540
	00855	400	400	3	710
	00856	400	500	3	880
	00857	500	500	3	1100
	00858	300	600	3	683
\$	00791	400	600	3	1100
	00859	500	1000	3	1900
	00860	1000	1000	3	3800
	00861	1000	2000	3	8000




**Rubber adapter mats, black**, made of synthetic elastomer. These mats can be milled and thereby achieve much better plane-parallelism

Other dimensions available on request

## Vac-Mat adapter plate

suggested for modular slot type chucks

Nr.	Α	В	C	Vac-Mats	kg
285136	300	200	10	10	2,7
285137	400	300	10	11	4,5
284497	600	400	10	12	8,1
				Aluminium a LO Vac-Mats	





Preference item: Articles with green diamond are available ex stock!





Slot vacuum chuck with 3 vacuum areas, which work combined or independently

# Slot vacuum chucks

Examples of special designs

 Slot vacuum chuck with special adapter plate

Slot vacuum chucks are particularly suitable for lighter cutting processes such as engraving, grinding, etc. parts with complex geometrical shapes, including those with cutouts (e.g. front panel).

Also working with adapter plates for multiple clamping is possible.

By using a rubber adapter mat it is possible to drill holes and to mill pockets and breakthroughs - without loss of vacuum. The adapter mat is 3mm thick, so a tool can penetrate about 2.5 mm into the adapter mat.





Circular vacuum chuck with ring slots for turning rings



Slot vacuum chuck mounted on a zero reference clamping system



Slot chuck with integrated rotation joint for use on an NC rotary table



View from below







## µ-porous Vacuum chucks

# Modular version in standard sizes or special design

These chucks have a porous surface area made out of sinterbronze, ceramic or porous aluminium depending on the application and workpiece. METAPOR<sup>©</sup> opens a whole new perspective for different clamping solutions

#### Application

Preferred workpieces:

- Thin walled (i.e. paper, foils, plate bars, metal strips)
- Fine (i.e. optical)
- Soft materials (i.e. rubbers)

#### for work such as:

- High precision measuring
- Precision milling
- Silicon wafer production

#### **Advantages**

- Due to the absence of grooves and holes workpieces are not deformed for instance on inserts in the clamping area
- Milling through the workpiece is possible with the use of our Friction booster
- METAPOR<sup>®</sup> has different quality grades and can also qualify for clean room surroundings (KI. 10)

#### Handling

- Modular chucks can be interconnected to enlarge the surface area.
- Part specific special designs available



## µ-porous Vacuum chuck

with METAPOR<sup>®</sup> CE100 White








Plate inlay in Metapor CE 100 WHITE fine porous material with low pore diameter and very homogenic total porosity





#### Supply includes:

- Modular Metapor<sup>™</sup> vacuum chuck
- 12x Height adjustable excentric end stops
- Vacuum chuck adapter
- 1m Vacuum suction hose with plug
- 2 x Step heel clamps, alu
- Tools for setting up

## µ-porous Vacuum chuck

with METAPOR<sup>©</sup> MC100 AL

Nr.	Α	В	C	kg
91021	300	200	38	5,7
92290	400	300	38	11,4
92291	600	400	38	23





Plate inlay in Metapor MC 100 AL fine porous material with low pore diameter and very homogenic total porosity, with larger porosity




#### Supply includes:


- Modular Metapor<sup>™</sup> vacuum chuck
- 12x Height adjustable excentric end stops
- Vacuum chuck adapter
- 1m Vacuum suction hose with plug
- 2 x Step heel clamps, alu
- Tools for setting up

Other Dimensions available on request. Further information on Metapor see page 89










#### Supply includes:


- Modular Metapor<sup>™</sup> vacuum chuck
- 12x Height adjustable excentric end stops
- Vacuum chuck adapter
- 1m Vacuum suction hose with plug
- 2 x Step heel clamps, alu
- Tools for setting up


## µ-porous Vacuum chuck

with METAPOR<sup>©</sup> BF100 AI

Nr.	А	В	C	kg
83401	300	200	38	5,7
84380	400	300	38	11,4
84381	600	400	38	23







Tools for setting up

## µ-porous Vacuum chuck

with METAPOR<sup>©</sup> HD 210

Nr.	А	В	C	kg
94315	300	200	38	6,1
94316	400	300	38	12,2
94317	600	400	38	25





Plate inlay in porous material Metapor HD210 AL for temperatures up to 210°C




## Sintermetal Vacuum chuck

Double layered, hardwearing sinterbronze inlay

Nr.	А	В	C	kg
84686	300	200	38	7,1
84687	400	300	38	14,2
84688	600	400	38	28,4






Tools for setting up

### **Friction Booster**

Protects Metapor chucks from damage when through cutting or lasering parts

Nr.	Α	В	C	Stck	kg
00839	300	200	<1	50	1,8
00840	400	300	<1	25	1,8
00841	600	400	<1	25	3,6



6000

30



Other Dimensions available on request. Further information on Metapor see page 84







Special version with integrated heating and electronic temperature control

# Vacuum Clamping Technology

# for new technologies in research and development

#### 1. Clamping with Witte vacuum chucks

Vacuum chucks from Witte have proven successful in many areas of semiconductor technology and made a name for accurate, fast and "gentle" clamping.

These lightweight, yet very accurate vacuum chucks are made of aluminum alloy and usually have a micro-porous clamping surface of Metapor material.

However, custom-built perforated-grid chucks with small holes arranged in a specific pattern can also be implemented. (See pictures)

#### 2. Flexible

Besides standard versions of this vacuum chucks, Witte offers every conceivable specific design and dimension. We analyze technical requirements and environmental conditions of customers' processes, and develop a concept together with them. Various technically feasible configurations have already been manufactured.

#### 3. Accurate

A modern machine shop and climatized measuring rooms with high precision measuring machines ensure excellent quality of products. Vacuum chucks are available with flatness and / or parallelism of <  $5\mu$ m if the application profile of the customer requires it.

#### 4. Reliability

A chuck surface comprising of micro-porous material guarantees completely "flat" clamping. Thin carrier foils or wafers are not deformed by suction holes, suction grooves or similar which occurs during conventional clamping methods. The low weight and accuracy of such Witte chucks is also advantageous for automated applications.

#### 5. Universal

Another major advantage of micro-porous vacuum chucks is that the vacuum still works extremely effectively even when the micro-porous surface is not covered completely. This enables clamping of different sized parts on the same chuck. The porous surface may also be divided into separately operable areas with individual switches. (See example opposite) Integrated hovercraft technology, ejector and lifting pins are some of the technical ingredients of these innovative concepts.

Furthermore, vacuum chucks for certain processes can be **"heatable"** up to a temperature as high as 150°C with corresponding temperature controls (see picture above.). Likewise, **cooling** systems or **light transparency** applications are possible.

#### 6. Everything from one source

In addition to standard and custom vacuum chucks Witte supplies all necessary accessories such as simple ejectors, vacuum pumps, rotary joints, hoses, solenoid valves and much more.


Our expert staff can advise you and look forward to your inquiry.



Specially designed porous chuck with three individual clamping areas, stops for part positioning and lifting pins for easy removal of wafers.




Flourescent chuck, 6" diameter



Finely milled vacuum chuck for clamping wafers, clamping area microporous material Witte MP CE100 WHITE flatness accuracy <0,005mm




Independent vacuum chuck. Clamping of parts on chuck completely free of external supply lines. Battery, vacuum pump, controls, display and valves are all integrated










DLC light transmitting chuck for clamping parts, views from above and below



Application in automotive industry, leather clamped on visible side for grinding predetermined breaking points in areas of airbags on reverse side

# μ-porous vacuum chucks

## **Further examples**



Same chuck shown without leather parts






Vacuum clamping system for laser application. Detail shows both clamping areas and cutting channels.

Small size micro finely machined chuck

Vacuum chuck with four separately usable clamping areas





## 58 µ-porous vacuum chucks







Vacuum chuck with three clamping areas and lifting pins for **manually** controlled process









# Sintermetal vacuum fixtures





Vacuum chuck for credit cards




Sinter metal vacuum chuck with special adapter plate for clamping hard metal blanks during laser machining process.

It has an integrated cooling labyrinth which prevents inaccuracies, due to development of warmth which occurs during the laser machining process







## **Custom built**

Surface area has many small bores. The large area enables secure clamping of sensitive work pieces such as foils used in printing or photographic industries.

These are only made to order according to customer data.

#### **Applications**

Highly accurate

 Clamping of films and foils on machines used to make printing plates during laser and UV exposure of films.
 Foils and conductors.

#### Advantages

- Sizes from 1.400x2.000 mm with an accuracy of 50 μm
- Vacuum clamping area need not be covered to 100%

#### Handling

- Easy positioning of workpiece with excentric end stops
- Only limited hold down force for machining purposes.









Vacuum clamping system with elevation function. On pult level valuable, sensitive prints and paintings are gently clamped using vacuum. Plate is raised automatically to vertical position and items are digitalized. Application takes place in a museum.

Vacuum clamping of carbon fibre part for accurate milling using Vilmill fleece







## Vilmill & Vacuum

#### Partners for high-speed cutting of aluminium and plastics

If your job is to cut lots of small parts out of one large part the combination of vacuum and Vilmill is what you need.

Vilmill is a vacuum system comprising of a fleece-like, coated foil, a specially equipped vacuum chuck and a powerful pump system for vacuum supply.

The Vilmill foil is mounted between chuck and part. The warmth created during cutting causes the surface coating to melt and sticks the part to the chuck.

The vacuum is effective through the Vilmill foil, which at the same time acts as a puffer. The accurately balanced permeability of Vilmill foil increases the efficiency of vacuum chucks and reduces vacuum consumption.

Especially when cutting out small parts Vilmill offers additional security through the adherence effect. It greatly simplifies removal of small finished parts from the machine.

For maximum cutting speeds a thin layer of material should remain in order to use the complete part surface under vacuum until the last cut is made.

Vilmill is suitable for aluminium or plastic sheets up to 15mm thick. Only dry machining is possible and the working range in Z axis must be high enough to integrate a vacuum chuck.

#### Conditions for use of VilmilI™

- Minimum suction 250-300m<sup>3</sup>/h
- High vacuum
- Spindle rpm > 20.000 <sup>1</sup>/<sub>min</sub>
- Grid hole type chuck with 10mm grid
- Suitable adapted milling strategy; tool must go in and leave part via programmed ramp

#### Vilmill<sup>™</sup>-Foil Black

#### • No. 600290

- Dim.: 0,35mm x 1000 x 100mm
- Weight per roll; 11,5kg (115g/m<sup>2</sup>)






Machining of thin metal sheets

The heat generated at the milling burr activates the adhesive coating on the mat and keeps even small parts in place.



Machining of aluminum sheets of greater thickness

Only the final feeding depth (0.1- 0.3 mm) cuts in the adhesive mat and separates the parts completely.



Machining of plastics

The adhesive coating is also activated during the machining of plastics and fiber compounds.



Vilmill adhesive foil

- Increase efficiency of vacuum chucks
- Fix parts during cutting
- Provide necessary space when material is cut through
- Are ideal for removing small parts after machining







# FLIP-POD<sup>™</sup> Vacuum System

## Alu FLIP-POD FLIP-POD

#### This technology is ideal for

- Milling
- Grinding
- Drilling
- Cutting threads

Mainly for large workpieces made out of

- Wood
- Plastic
- Glass
- Cast metals

Suitable for


Milled or rough surfaces.

#### Advantages

- Strong hold down forces enable the use of large machines.
- Bevels, contours and radii can be performed on the upper and lower workpiece surfaces.
- Clamping dimensions can be changed within seconds to conform to new workpiece sizes
- Can be used on most machine tables.

#### Handling

- Pods are the contact surfaces fort the workpiece
- Simply activate or deactivate the pods by turning them around.
- To clamp a workpiece effectively 6-8 pods are required.
- This modular system can be extended for larger clamping surfaces.



#### Alu FLIP-POD™

has an accurate, defined workpiece surface. Height tolerance is only  $50\mu$ . They are suitable for face machining on both surfaces, especially of metallic workpieces.





#### Function

The round polymer pods (1) protrude out of the pod plate when in use.

The pods not required lie in a recess cavity (2) of the pod plate.


Simply flipping them over activates or deactivates the pods. The valve ball which stops the vacuum supply when the pod is resting, opens the valve and the vacuum system is activated.


All active pods stand 27mm above the pod plate surface, allowing contour milling and recess cutting on the outer contours.




65







- FP Seal
- FP BallFP Filter



## FP Basic unit


complete

**FP Seal** 

Nr.	Α	В	C	C Mat	
84408	70	88	31	Aluminium	170
14384	70	88	31	Polymer	100








## **FP Polymer Ball**






## **FP** Filter






## FP Large seal


for Pod Plate





## FP Center hole gasket

for pod cavity















The sketches show a range of possible pod panel designs.



The user can choose a panel design that best suits the parts being machined. The pod panel can be laid out in almost any design and combination.

### **FLIP-POD<sup>™</sup> Sets**

polymer version

Nr.	Description	Area/Grid	Pods (N)	kg
83100	FLIP-POD <sup>™</sup> Set 100	1m²/100mm	100	10,2
83200	FLIP-POD <sup>™</sup> Set 200	2m²/100mm	200	20,2
83300	FLIP-POD <sup>™</sup> Set 300	3m²/100mm	300	30,2
83400	FLIP-POD <sup>™</sup> Set 400	4m²/100mm	400	40,2




#### Supply includes:

- Basic unit with lip seal
- FP Center hole gasket
- FP Large seal
- 3 Retractable locator pod
- 2 Fixed locator pods






## **FP Lift ring**





#### **FP** Transfer Pod B C Nr. A Dg Ε F g **85662** 88,9 874 50,8 30 51 55,9 230 G





Acts as spacer when positioning large workpieces, raised ring retracts when vacuum is applied

## FP Half Pod (1/2)

Nr.	А	B Mat		g
85328	88	30,9	Aluminium	150
82138	88	30,9	Polymer	95















## FP Retractable locator pod

automatically retract when vacuum is applied

Nr.	A	В	C	D	E	F	g
82136	88,9	74	50,8	14,4	38,6	62,3	252
		6					upper sec witched



## FP Fixed locator pod


incl. unit, pins and spacer disks

Nr.	A	B	C	D	E	F	G	Н	ğ
82137	88,9	74	28,6	47,8	12,7	76,3	15	25,5	476



#### Fixed and retractable locator pods

ensure high accuracy. Locator pods are available in both fixed and retractable versions, either of which fit in any pod cavity. After positioning the workpiece the retractable pods are drawn back into the pod plate as soon as vacuum is switched on, allowing a free path for the cutting tool.









Various Flip-Pod<sup>™</sup> applications in different industries i.e. aircraft and carriage building










# Accessories and replacement materials



# **Replacement materials**



VAC-MAT™ Page 30

Rubber adapter mat, blue Page 46

Rubber adapter mat, red Page 46

Rubber adapter mat, black Page 47

Friction Booster Page 53

**Vilmill™** Page 62

**O-shaped seal** Page 74

Wire spiral hose Page 83

Polymer hose Page 83

Polymer tubing Page 83



# Vacuum Switch with LED Display

Vacuum switch, electronic, with adjustable safety values. Used as safety switch for <u>dry</u> working environments.

Nr.	Maße (mm)	U	g
282703	55x30x32	24V	11

#### Technical data:

<ul> <li>Measuring ran</li> </ul>	ge:	-1 to + 10 bar	
Connection:		G1/8"	
<ul> <li>Operating curr</li> </ul>	ent (V):	18-32 DC	
<ul> <li>Electricity load</li> </ul>	(mA):	100	
<ul> <li>Compression r</li> </ul>	esistance (bar):	20	
<ul> <li>Readiness dela</li> </ul>	Readiness delay time (s):		
<ul> <li>Min. reaction t</li> </ul>	Min. reaction time switch off (ms):		
<ul> <li>Adjustable dela</li> </ul>	<ul> <li>Adjustable delay time sD, dr (s):</li> </ul>		
Protection:		IP 65	
<ul> <li>Weight (kg):</li> </ul>		0,106	
Display:	Display unit	4 x LED green	
	Switching status	2 x LED yellow	

#### **G** Supply includes:

Connecting cable 5m, angled

#### Operation manual

# Vacuum Switch with LED Display

Vacuum switch, electronic, with comprehensive adjusting/programming possibilities. Used as safety switch for <u>wet and explosion</u> <u>protected</u> working environments.

Nr.	Maße (mm)	U	g
283126	h=92, ø33	24V	50
	Nr. 283126		

#### **Technical data:**

- Vacuum display, controlled electronically
- Upper and lower vacuum safety values (hysteresis) freely adjustable
- Connection: G1/4"
- Adjustable reaction time
- Programming of switching outputs
   Hno = Hysteresis /Closer
   Hnc = Hysteresis /Opener
   Fno = Hysteresis /Closer
   Fno = Hysteresis /Opener
- (Close contact/break contact)
- Maximum overload pressure 10bar



#### Supply includes:

Connecting cable 5m, angledOperation manual



Preference item: Articles with green diamond are available ex stock!







### Vacuum grease

Nr.	Description	Inhalt	ġ
80140	Grease	250g	350

#### Used from time to time for the following:

- Greasing suction hose
- Sealing off workpieces with rough or scored surface



**80103** Axial connection



Radial connection

### Vacuum gauges

	Connection-	Dia-	Range	g
Nr.	thread	meter		
80103	G1/8" axial	ø40	0 to -1 bar	40
80100	G1/8" radial	ø40	0 to -1 bar	40



Used for sealing grid chucks or defining active vacuum areas. This high quality seal is placed into the slot of a grid type vacuum chuck.

The seal diameter is dependent on the cross section of the slot. If a plate is milled over then a seal with a smaller diameter will be required.

Minimum order quantity 50m/per diameter.

### **O-shaped seal**

	Nr.	Diameter		Nr.	Diameter
•	00188	ø 2,0mm	_	00171	ø 5,5mm
	00069	ø 3,0mm		00072	ø 6,0mm
	00170	ø 3,5mm		00172	ø 6,5mm
	00070	ø 4,0mm		00073	ø 7,0mm
	00157	ø 4,5mm	-	00251	ø 8,0mm
	00071	ø 5,0mm		00316	ø 10,0mm
	_				

**Tolerance class:** DIN ISO 3302-1 Tab. 2. Class E3



Preference item: Articles with green diamond are available ex stock!




# Manifold distributors

All manifolds are supplied with corresponding hose-nozzles and on each exit there is a 3/2 way aerated vacuum valve with a vacuummeter

The manifold can be upgraded to a safety appliance when assembled together with a safety pressure switch ( 93937 or 282703, see page 85). Connection threads R 1/8" with blind plugs are already in place.

Nr.	A	В	C	D	kg
94045	250	43	2xLW12	1xLW18	1,5
92419	250	43	3xLW12	1xLW18	2
84389	300	43	4xLW12	1xLW18	1,7
85680	250	43	3xLW18	1xLW25	2
84390	480	84	6xLW12	1xLW25	5,6
85197	294	53	4xLW12	1xLW32	3
84391	480	84	6xLW12	1xLW32	5,9
84591	510	84	4xLW18	1xLW32	6,5
84392	765	84	6xLW18	1xLW32	6,9
89052	510	84	2xLW25	1xLW32	6,5
90134	690	84	6xLW12	1xLW50	6,9
90177	440	84	3xLW18	1xLW50	5,5
84393	510	84	4xLW25	1xLW50	6,0
90562	650	84	5xLW25	1xLW50	6,5
90527	130	84	2xLW32	1xLW50	4,6
84394	510	84	4xLW32	1xLW50	6






# Y distributor with female thread

Nr.	Thread	Hose nozzle	g
90716	G3/8"	3 x ø12	170
90717	G1/2"	3 x ø18	900
90718	G1/2"	1 x ø18, 2 x ø12	1000











#### Supply includes:

- 3/2 way aerated valve
- 3m vacuum hose
- 1 vacuummeter
- 2 hose fittings


### **Connection unit**

Nr.	Туре	For hose dia
80102	straight	12mm
82519	straight	18mm
82952	straight	24mm
82902	straight	32mm
82953	straight	50mm



# Slide valve

Nr.	Α	В	C	D	E	g
81322	48	25	13	SW14	G1/8"	50
11252	58	30	16	SW17	G1/4"	85
81324	70	35	20	SW22	G3/8"	180
82961	80	40	25	SW26	G1/2"	217
19121	83	49	30	SW32	G3/4"	380



# Vacuum hand valve

Nr.	Connection thread	Тур	<b>S</b>
85625	1/4" female/female	-	70
80139	3/8" female/female	-	99
13444	3/8" female/female	mini	69
80988	1/2" female/female	-	149
11453	3/4" female/female	-	500
82927	1" female/female	-	604
80563	1 1/4" female/female	-	800
83144	1 1/2" female/female	-	900



# Foot switch

Nr.	Connection	Operation	kg
80322	G1/4"	pneumatic	2,4
16420	250-400V AC, 24V DC	electric	0,7

#### **G** Supply includes:

- 2 hose fittings
- 2x3m vacuum hose with wire spiral 18/12








10

焰


53

# Vacuum electro-magnetic valves





















# Vacuum electro-magnetic valves

#### Normal open, DC 24V

Nr.	Connection thread	Pump max. m <sup>3</sup> /h	Vacuum min.	kg
90960	1/4" female/female	4	150 mbar	0,58
80908	3/8" female/female	10	150 mbar	0,8
90961	1/2" female/female	20	150 mbar	1,19
84204	3/4" female/female	60	150 mbar	1,13
82997	1" female/female	90	150 mbar	1,9
84275	1 1/2" female/female	180	150 mbar	2

### Seals

for electromagnetic valve

Nr.	for valve nr.	ġ
16328	90960	9
11108	80908	9
11178	90961	14
111 <b>78</b>	84204	14
12210	82997	80
12365	84275	80

# Vacuum electro-magnetic valves

Type "ECO", normal open (NO), AC 230v

Nr.	Connection thread	Pump max. m <sup>3</sup> /h	Vacuum min.	kg
19191	1/2" female/female	20	150 mbar	-
19193	3/4" female/female	60	150 mbar	-
19194	1" female/female	90	150 mbar	-
19196	1 1/2" female/female	180	150 mbar	-

### Seals

for electromagnetic valve


Nr.	for valve nr.	g
19192	19191/19193	20
19195	19194	35
19197	19196	70












Universally used dust filter, dirt immediately visible through transparent housing. Designed to allow easy exchange of cartridge, whereby filter seals must also be changed. A fitting filter cartridge is included in package.

## Airfilter

suction filter for vacuum pumps, units etc.

Nr.	A	В	C	Filter#	g
83324	105	110	3/4"	80142	560
83322	140	120	1 1/4"	80143	760





### Seal

for airfilter

Nr.	pcs	size	for filter#	ğ
29482	1	small	83324	1
29483	1	big	83324	3
21059	1	small	83322	1
29464	1	big	83322	5

 2 large and 2 small seals are required when exchanging one air filter



### Screw hose connection

Nr.	Thread	for hose inner dia.	g
10632	3/8"	9	34
83322	1/2"	12	45



# Double nipple

detachable

Nr.	Thread	<b>S</b>
10301	1/8" male/male	9
12095	1/4" male/male	40
12110	3/8" male/male	52
12072	3/4" male/male	196
11479	1" male/male	351



# **Bulkhead fitting**

enabling feed through for machine tools

Nr.	Name	g
288455	Bulkhead fitting LW19 x LW 19	160
288456	Bulkhead fitting LW19 x LW 13	150
288457	Bulkhead fitting LW13 x LW 13	140
288458	Bulkhead fitting LW19 x SK-NW 7	230
288459	Bulkhead fitting LW13 x SK-NW 7	210
289607	Bulkhead fitting LW32 x LW32	200



## Reducer

male/female

Nr.	Thread male	Thread female	ğ
10542	1/4"	1/8"	11
10681	3/8"	1/8"	20
12113	3/8"	1/4"	100
10302	1/2"	1/8"	40
10743	1/2"	1/4"	51
10299	1/2"	3/8"	22
11455	3/4"	1/8"	51
10896	3/4"	3/8"	66
10316	3/4"	1/2"	36
12107	1"	3/8"	11
12108	1"	1/2"	90
10636	1"	3/4"	98
12109	1 1/4"	1/2"	199
12359	1 1/2"	1"	206
10637	2"	1 1/2"	229









# Quick coupling

with male thread

Nr.	Thread	for plug#	g
80104	3/8"	10271 10275 10519	77
80989	1/2"	10271 10275 10519	86
80441	3/4"	12079	130



# Plug

for quick coupling

Nr.	for hose inner dia.
10271	ø 6
10275	ø 8
10519	ø 13
12079	ø 19




# Hose nozzles

11561         1/8"         Ø 9           10638         1/4"         Ø 9	14
<b>10638</b> 1/4" Ø 9	
	17
<b>11768</b> 1/4" ø 13	17
<b>10354</b> 3/8" Ø 9	19
<b>10269</b> 3/8" Ø 13	19
<b>10270</b> 1/2" ø 13	24
<b>11508</b> 1/2" ø 19	22
<b>11509</b> 3/4" ø 19	32
<b>11746</b> 3/4" ø 25	32
<b>11726</b> 1" Ø 25	37
<b>10471</b> 1" Ø 32	37
<b>10598</b> 1 1/4" Ø 32	50
<b>11620</b> 1 1/2" ø 50	53
<b>11468</b> 2" Ø 50	57



# Vacuum polymer hose

Nr.	Description	Dim
17793	Vacuum tubing	ø 6/4
17794	Vacuum tubing	ø 8/5
17795	Vacuum tubing	ø 10/8
17796	Vacuum tubing	ø 12/9



# Vacuum polymer tubing

Nr.	Description	Dim
00058	Vacuum hose	ø 6/8
00059	Vacuum hose	ø 12/8
00132	Vacuum hose	ø 15/12
00057	Vacuum hose	ø 10/6
00902	Vacuum hose	ø 22/18



# Wire spiral hose

nner ø	outer	Bendable radius (min., static)	Nr.	
3/8	Ø	20 mm	00717	
/12	ø 1	25 mm	00060	
/18	ø 2	40 mm	00061	•
/25	øЗ	60 mm	00253	
/32	ø4	75 mm	00184	
/50	øe	125 mm	00185	
/25 /32	ø 3 ø 4	60 mm 75 mm	00253 00184	<b></b>



# Wire spiral hose HD

suitable for energy chains

Nr.	Bendable radius (min., dynamic)	outer / inner ø
18801	32 mm	ø 13,5/8
18805	45 mm	ø 18/12
18795	80 mm	ø 28/19
18796	90 mm	ø 35,5/25
18797	110 mm	ø 42,5/32
18798	170 mm	ø 63,5/50









### WITTE-METAPOR<sup>®</sup> - Porous aluminium

Instead of bores for vacuum and air pressure - METAPOR® for vacuum and air pressure!

This unique porous aluminium compound material is suitable for die and mould, conveyance and clamping systems

Evacuation


vacuum mould-forms made of METAPOR<sup>•</sup> vacuum chucks made of METAPOR<sup>•</sup> i.e. for clamping electronic workpieces and foils

- Lifting air film glide handling equipment made of METAPOR<sup>o</sup>
- Through flow for agitating bases and conveyor channels made of METAPOR<sup>•</sup>
- Molding/Demoulding deep drawn and die moulds made of METAPOR<sup>•</sup>
- Ceramic and machined forms made of METAPOR<sup>o</sup>





# WITTE - METAPOR<sup>®</sup> - Applications



#### Vacuum clamping technology

The main feature of METAPOR<sup>®</sup> vacuum clamping systems is suction over the complete surface area without suction bores.

Foils are held absolutely flat. The pressure drop, which takes place within the structure means that it is not necessary to cover areas not in use. METAPOR<sup>®</sup> is ideally suited for holding foils and electronic parts as well as for mould-forms and soft workpieces.




#### Air film glide technology

The pressure distribution in the METAPOR<sup>®</sup> structure allows even surface airflow capacity, even if only part of the surface is covered. Air consumption and noise emission are considerably reduced. Trouble-free machining offers cost reduction on air flow components, a new perspective for rotation bearings, conveyance and extrusion beds.



#### Through-flow technology

The microporous METAPOR<sup>®</sup> structure allows an even agitation of granulates and powders without bubbles ocurring. Low air consumption reduces friction and mechanical load. METAPOR<sup>®</sup> ideal for mixing processes, coating, conveyance troughs and dismantling of silo bridges



#### Mould technology

Deep drawn moulds made of METAPOR<sup>®</sup> do not require any bores. Bore imprints on the workpiece are avoided. Suction over the complete area allows structures to be complex without air pockets and distortions. The complete flow-through of air prevents high-temperature areas developing. Rational machining procedure and immediate usability promise a valuable technological advantage





## Witte METAPOR<sup>®</sup>- material properties

METAPOR<sup>®</sup> is made mainly out of two components: Granulate (e.g., Aluminium, Ceramic) and a binder e.g., epoxy, polyester, polyurethane).

These different components influence the qualities and behaviour of the material. For example porosity, hardness, temperature consistency, and surface finish.



The machineability of METAPOR<sup>®</sup> is excellent and can be compared to easily machineable aluminium. METAPOR<sup>®</sup> is machined without coolant in order to keep the pores clean Better surfaces are achieved with high cutting values. No noticeable warmth developing in the workpiece can be felt during machining.

<code>METAPOR®</code> is available in the standard sizes 500x500mm, thickness from 10 - 100mm (  $\pm 0,3mm$ )

Larger plates (i.e. 1m<sup>2</sup> oder 2m<sup>2</sup> glued plates supplied on request)

#### **METAPOR©-Materials in comparision:**

	BF 100 AL	MC 100 AL	CE 100 White	HD 210 AL
Porosity	15%	17%	20%	16%
Max. temp.	100°C	100°C	100°C	210°C
Strength yield	**	*	****	**
Thermo- forming	**	*	*	***
Vacuum clamping	****	***	****	****
Average pore ø	approx. 15µm	approx . 40µm	< 10µm	approx . 12µm

 $\star \rightarrow \star \star \star \star =$  Increase in suitability



# Witte METAPOR<sup>®</sup> materials

Nr.	lxbxh	kg
600839	500x500x10	4,0
600840	500x500x15	6,0
600841	500x500x20	8,0
600842	500x500x25	10,0
600843	500x500x30	12,0
600844	500x500x35	14,0
600845	500x500x40	16,0
600846	500x500x50	20,0
600847	500x500x60	24,0
600848	500x500x70	28,0
600849	500x500x80	32,0
600850	500x500x100	40,0



#### MC 100 AL

METAPOR<sup>°</sup> material with maximum porosity

- Density: 1,7 g/cm<sup>3</sup>
- Strength yield: 25,0 N/mm<sup>2</sup>
- Max. Temp: 100,0 °C
- Thickness tol.: -0/+0,3 mm

Nr.	lxbxh	kg
00513	500x500x10	4,5
00552	500x500x15	6,8
00553	500x500x20	9,0
00554	500x500x25	11,3
00555	500x500x30	13,5
00556	500x500x35	15,8
00557	500x500x40	18,0
00558	500x500x50	22,5
00559	500x500x60	27,0
00560	500x500x70	31,5
00561	500x500x80	36,0
00562	500x500x100	45,0



#### **BF 100 AL**

Standard quality with good allround properties


Density:	1,78	g/cm <sup>3</sup>
<ul> <li>Strength yield:</li> </ul>	56,0	N/mm <sup>2</sup>
<ul> <li>Max. Temp:</li> </ul>	100,0	°C
<b>T</b> 1 ' 1 ' 1 '	0/ 0.0	

■ Thickness tol.: -0/+0,3 mm









# Witte METAPOR<sup>®</sup> materials

Nr.	lxbxh	kg
00244	500x500x10	4,0
00245	500x500x15	6,0
00246	500x500x20	8,0
00247	500x500x25	10,0
00248	500x500x30	12,0
00288	500x500x35	14,0
00249	500x500x40	16,0
00289	500x500x50	20,0
00250	500x500x60	24,0
00292	500x500x70	28,0
00293	500x500x80	32,0
00252	500x500x100	40,0

#### HD 210 AL

METAPOR<sup>°</sup> material with high temperature resistance

	Density:	1,9	g/cm³
--	----------	-----	-------

- Strength yield: N/mm<sup>2</sup> 43,0
- Max. Temp: 210,0
- °C Thickness tol.: -0/+0,3 mm



#### CE 100 White

METAPOR<sup>°</sup> material with very hard surface properties and low porosity


	Density:	1,7	g/cm³
--	----------	-----	-------

- Strength yield: 24,0 N/mm<sup>2</sup>
- 100,0 °C Max. Temp:
- Thickness tol.: -0/+0,3 mm











Metapor chuck in analysis application

Rotary vacuum clamping chuck with  $\ensuremath{\mu \text{porous}}$  clamping surface



Double chuck system with two clamping surfaces which can be very accurately aligned to one another









# ICEVICE<sup>©</sup> Freeze clamp technology

#### When to use this technology

This is ideal technology for clamping smalll or intricate workpieces without any tension yet accurately.

For machining mechanically or to separate small parts from a large unit of raw material.

Favoured by the following industries;

- Electronics / Semi-conductors
- Ceramics
- Optics, Glass / Quarz treatment
- Metals, clocks and watches
- Medical tools and laboratory equipment
- For universities and research.

#### Advantages

- Very precise up to  $\pm 3\mu m$
- No tension builds up within the workpiece
- Short clamping time +/- 90 seconds.

#### Handling


- Easy and quick
- With the use of workpiece specific adapter plates a high degree of repeatability in positioning and clamping is achieved

#### Function

- Freezing generated by compressed air
- Chuck surface in aluminium with very good warmth drawing properties
- Housing in special polymer with insulation



### Clamping by freezing on a thin water film






When clamping with the lce-Vice system parts are frozen to chuck surface on a capillary film of water for machining. Even relatively uneven parts can be clamped as any gaps are filled with water. The vertical and horizontal clamping forces created are enough to hold small parts for milling, grinding, drilling or polishing.

### Ice Vice Clamping System

Nr.	Dim	Clamping surf.	kg
282364	300x140x75	150×100	4,3
283209	300x200x100	250x150	9

#### Supply includes:

- 0,5m hose inside Dia 9 with connection fittings
- Plastic case with inlay




To improve production time ICEVICE<sup>®</sup> can also be palletized where a quick exchange of Freeze plates is possible. These plates have a vacuum connection to ensure secure fixation to the Icevice base.





### Witte Weiguss mould clamping technology



**Witte Weiguss** mould clamping technology is suitable for manufacturing workpieces, which cannot be clamped conventionally because support surfaces are lacking.

**Application:** Clamp the unmachined workpiece onto i.e. a Vac-Mat<sup>™</sup> vacuum chuck. The top surface is milled conventionally.

The milled hollows are filled with melted Weiguss alloy, which hardens into a plane parallel surface. The workpiece is then turned around 180° and clamped securely on to the vacuum chuck. Stop pins make sure the workpiece is positioned accurately.

The finished workpiece is placed into warm water at 80°C in order to melt the alloy attached to it. The alloy does not mix with water and can be collected, remelted and used again.

### Witte Weiguss LM70

Nr.			kg
94161	Weiguss- Pack	to 1kg	1

#### Supply includes:

- CD Rom with video
- Technical information as a PDF file

#### Special advantages:

Witte Weiguss mould clamping method is especially suitable for complicated or spherical shaped parts. Unlimited reuse.






Left: First step is milling workpiece conventionally



Top: Finally workpiece is placed in water at 80°C to melt and remove alloy, which can be reused

Right: Filling hollow with melted Witte Weiguss alloy



Right: After hardening, workpiece is turned over and machined on reverse side





Witte Weiguss is especially suitable for complicated workpieces with curved or concave surfaces





# Vacuum Base

for measuring arm

# Measuring arm secured in seconds

This universal vacuum base is the ideal partner for measuring arms. A battery operated miniature pump creates sufficient vacuum so that the base sucks itself on to all kinds of surfaces in seconds.

Control display, lamp indicators and pressure switch ensure safe and secure mounting. Operating and control lights are integrated into the compact design. Holes in the top surface allow mounting of adapter rings (not included) for measuring arms of leading manufacturers. The Witte vacuum base requires no additional equipment. Applications away from other energy sources are possible. A special seal even allows mounting on curved surfaces, which expands application possibilities considerably. Description: Vacuum Base Item number: 282446B Dimensions: ca. Ø 260 x 80mm Weight: 5,6Kg Holding force: max. 4200Newton (at sea level) Charger: Voltage from 100 to 240 Volt



Operating voltage of charge 12 Volt

LEDs show loading condition of battery

Acoustic signal when vacuum drops below set level

Set end vacuum 200mb absolute This corresponds to relative end vacuum of 80%

Measuring arm and adapter ring are not included.







### Contents and user details.

- 1 ON / OFF switch
- 2 Indicators for battery charging levels Red / Yellow / Green
- 3

7

- Vacuum indicator
- Threaded bores for the different types of measuring arms
- 5 Battery charger input plug
- 6 Vacuum release screw (Take care to support measuring arm when screw is released)
  - Seal on Vacuum plate base

### Six steps on how to operate:

- 1 Place plate on clean worksurface.
- 2 Make sure vacuum release screw (6) is closed
- 3 Switch on using ON/OFF switch (wait 5 seconds for vacuum to reach operating mode)
- 4 Check battery status red/yellow/green LED'S
- 5 Vacuum dial gage (3) value must show 0,7 0,8



#### 96 Vacu-Vice




# Vacu-Vice clamping system

Vacu-Vise is a clamping method using vacuum as an alternative to conventional vises operated pneumatically, hydraulically or mechanically.

This clamping system consists of a specially designed vacuum chuck and two clamping jaws, which are mounted on a rigid, but resiliently deformable support plate. When vacuum is switched on, the support plate is drawn downwards and deformed in such a way that the clamping jaws tip towards each other and thereby clamp the work piece securely with great force.


Especially advantageous - when a vacuum supply is already in use on a machine - this new clamping method offers an extended effective use of the "medium" vacuum. Wherever dimensions of a work piece


and cutting forces no longer permit conventional vacuum clamping, there is now a possibility of strong and if necessary additional form-fitting work piece clamping with this new clamping system.



For example, if on a milling center several consecutive processes require re-clamping of a part and the remaining surfaces for direct vacuum clamping are too small, this innovative clamping technology can be used.

One system has already been implemented in the medical field, and amongst other things is in use for manufacturing plastic elements for knee implants.








ALC

79

Machine table (3,3x11 meters) supplied with VAC-MAT<sup>™</sup> Vacuum clamping. The photo shows the fixture at an aircraft manufacturer, where pockets are milled into a surface area covered with 468 Mats.



CNC milling machine equipped with a vacuum system used in house for precision-machining aluminium aircraft parts



Vacuum chuck for clamping bottles tops during measuring by coordinate measuring machine

2 Rotating systems (each 3500mm) with vacuum clamping areas on all four sides for machining aluminium profiles





Roller bar vacuum system for precision machining pre-formed aluminium sheets





Combined special clamping system made out of Witte VAC-MAT<sup>™</sup> and FLIP-POD<sup>™</sup>


Vacuum fixture with hydraulic components for machining steel parts



Clamping fixture for machining cylindrical pre-formed ai craft fuselage parts (13m x 4,10m) Parts are pressed down, rolled flat and clamped using vacuum as well as pneumatic and hydraulic clamps

C COURCE






Vacuum chuck for clamping lap-top housings




Chuck for chip cards



Special designed automatic liquid separator for integration in custom built system



Circular chuck ø 1500 mm





10

Vacuum Fixture for drilling operation, approx. 4600mm long, with additional manually clamps

	0 0 0	0 0 0	0 0 0	0 0 0	0 0 0 0		4 4 4	0 0 0	0 0 0	0 2 0				and the second second
	0	3	0	3	0	0	0	0 0		0	2 2	3	2 2	
	0 0	0 0	0	0	0 0	0 0	0 0	0 0	4 4	0	2 2	4 4	3	
a z z ministre	0	0	0	3	3	a	a	3	0	0	3	3	3	Ì
	0	0	о 0	0 0	0	0 0	0 0	3	3	0 0	0 0	0	3	
	5	3	3	0	3	3	0	3	3	0	0 0		2 2	
	0	3	0	0 0	0 0	0 0	0	0 0	0 0	3		4	-	
A REAL PROPERTY AND A REAL	3	0	3	•	0	3	3	3	0	3	2	•	4	

Vacuum cube with integrated storage tank and distribution manifold, approx. 800 x 800 x 900 mm, used on machining centre with automatic 24 hour pallet exchange system. Parts held with vacuum during machining, transport and standing times.






### Vacuum conversion table

%Vakuum	kPa	mbar	Torr	-kPa	-mmHg	-inHg
100	0	0	0	101,3	760	30
90	10	100	75	90	675	27
80	20	200	150	80	600	24
70	30	300	225	70	525	21
60	40	400	300	60	450	18
50	50	500	375	50	375	15
40	60	600	450	40	300	12
30	70	700	525	30	225	9
20	80	800	600	20	150	6
10	90	900	675	10	75	3
0	101,3	1013	760	0	0	0

### Additional holes in modular chucks

not for modular slot type chucks



### **Friction coefficients**

and their influence on vacuum clamping technology

Material	Gr	ip µ <sub>o</sub>	Friction $\mu$			
Waterial	dry	lubricated	dry	lubricated		
Steel/Steel	0,15	0,1	0,1	0,07		
Steel/Casting	0,25	0,1	0,2	0,08		
Steel/Brakepad	-	-	0,5-0,6	0,2-0,5		
Steel/Polyamide	_	-	0,32-0,45	0,1		
Steel/Ice	0,027	-	0,014	-		
Wood/Wood	0,4-0,6	0,2	0,2-0,4	0,1		
Wood/Metal	0,6-0,7	0,1	0,4-0,5	0,1		
Rubber/Asphalt	0,7-1,0 ( >1,0)	-	0,5-0,6	_		

Atmospheric pressureAt sea levelOm $1013 \\ mbar$ On the Zugspitze2963m $695 \\ mbar$ On Mount8848m $330 \\ mbar$ Pormula for determing horces $330 \\ mbar$ Formula for determing horcesThe pressure P is the result of the ratio to force F and area AF= P x A = NExample: Vacuum unit with under pressure of 85% vacuum. Whereby P = 0,85 bar = 0,85 N/cm2 A = 40cmx60cm = 2400 cm2 F = 0,85 N/cm2 x 2400 cm2Units: P=N/cm2 F = N									
At sea levelOmmbarOn the Zugspitze2963m $695$ mbarOn Mount8848m $330$ mbarFormula for determing holding forces $330$ mbarThe pressure P is the result of the ratio to force F and area AF= P x A = NExample: Vacuum unit with under pressure of 85% vacuum. Whereby P = 0,85 bar = 0,85 N/cm² A = 40cmx60cm = 2400 cm² F = 0,85 N/cm2 x 2400 cm² F = 0,85 N/cm2 x 2400 cm² F = 0,85 N/cm2 x 2400 cm²Units: P= N/cm²	Atmospheric	pressure							
Zugspitze $296.3$ mmbarOn Mount8848m $330$ mbarFormula for determing holding forces $330$ mbarThe pressure P is the result of the ratio to force F and area AF= P x A = NExample: Vacuum unit with under pressure of 85% vacuum. Whereby P = 0,85 bar = 0,85 N/cm² A = 40cmx60cm = 2400 cm² F = 0,85 N/cm2 x 2400 cm²Units: P= N/cm²	At sea level	Om							
Mount8848m330 mbarEverestmbarFormula for determing holding forcesThe pressure P is the result of the ratio to force F and area A $F=P x A = N$ Example: Vacuum chuck 40 x 60 cm; Vacuum unit with under pressure of 85% vacuum. Whereby P = 0,85 bar = 0,85 N/cm² A = 40cmx60cm = 2400 cm² F = 0,85 N/cm2 x 2400 cm² = 20400 NUnits: P= N/cm²		JUG 3m							
forces The pressure P is the result of the ratio to force F and area A $F=P \times A = N$ Example: Vacuum chuck 40 x 60 cm; Vacuum unit with under pres- sure of 85% vacuum. Whereby P = 0,85 bar = 0,85 N/cm <sup>2</sup> A = 40cmx60cm = 2400 cm <sup>2</sup> F = 0,85 N/cm2 x 2400 cm <sup>2</sup> = 20400 N Units: P= N/cm <sup>2</sup>	Mount	8848m							
The pressure P is the result of the ratio to force F and area A $F= P \times A = N$ Example: Vacuum chuck 40 x 60 cm; Vacuum unit with under pres- sure of 85% vacuum. Whereby P = 0,85 bar = 0,85 N/cm <sup>2</sup> A = 40cmx60cm = 2400 cm <sup>2</sup> F = 0,85 N/cm2 x 2400 cm <sup>2</sup> = 20400 N Units: P= N/cm <sup>2</sup>		terming I	nolding						
Vacuum chuck 40 x 60 cm; Vacuum unit with under pres- sure of 85% vacuum. Whereby P = 0.85 bar = 0.85 N/cm <sup>2</sup> A = 40cmx60cm = 2400 cm <sup>2</sup> F = 0.85 N/cm2 x 2400 cm <sup>2</sup> = 20400 N Units: P = N/cm2	The pressure P is the result of the ratio to force F and area A								
$A = cm^2$	Vacuum chuc Vacuum unit v sure of 85% v Whereby P = 0,85 bar = A = 40cmx60 F = 0,85 N/cr = 20400 N Units: P= N/cm <sup>2</sup> F = N	vith unde acuum. = 0,85 N cm = 24	/cm <sup>2</sup> 400 cm <sup>2</sup>						

The higher the number, the higher the resistance is against the work piece moving when clamping with vacuum. This resistance is reduced when water, coolant or oil is involved. Depending on the two materials involved up to 5 times as much. For instance steel on steel has a friction coefficient of 0,15. The value drops to 0,7 when using fluids. This shows clearly how clamping forces can be negatively affected when coolants are involved.



### Index

3D Vacuum chuck 38 µ-porous Vacuum chuck 50 Δ Accessories 72 Additional vacuum tank 13 Airfilter 80 R Bulkhead fitting 81 **Business activities 2** С Choosing a vacuum unit or pump 8 Choosing vacuum supply 9 Circular chuck 39, 102 Circular Grid Vacuum Chucks 39 Clamping with vacuum 24 Compact System 19 Connection unit 76 D DLC 56.58 Double nipple 81 Ε electro-magnetic valve 78 end stop 31 F FLIP-POD 64 FLIP-POD Function 65 FLIP-POD Sets 68 Flourescent chuck 55 Foot switch 77 FP Basic unit 66 FP Center hole gasket 67 FP Filter 66 FP Fixed locator pod 70 FP Half Pod 69 FP Large seal 67 FP Lift ring 69 FP Polymer Ball 66 FP Retractable locator pod 70 FP Seal 66 FP Transfer Pod 69 Freeze clamp technology 90 Friction Booster 53 Friction coefficients 104 G Grid chuck - modular 34 Grid chuck - standard 35

Grid chucks 32 Grid vacuum chuck Starter Sets 36 н Hand valve 77 Height adjustable end stops 31 Hose connector 30 Hose nozzle 82 **ICEVICE 90** Independent vacuum chuck 55 Light transmitting chuck 56, 58 Liquid ring vacuum pump 14 Liquid separator 20 Liquid separator, automatic 21, 102 LM70 92 М Maintenance kits 13 Manifold distributors 75 **METAPOR 84 METAPOR - Applications 85** METAPOR- material properties 86 Modular Slot Vacuum Chuck 41 Modular vacuum unit 16, 17 Mould clamping technology 92 0 O-shaped seal 34, 74 P Perforated grid chuck 60 Plug 31, 82 Polymer hose 83 Polymer tubing 83 Porous aluminium 84 Q Quick coupling 82 R Reducer 81 Replacement materials 72 Roller bar 99, 101 Rotation joint 76 Rubber adapter mat 46 S Screw hose connection 80 Seal 34, 79, 80 Sealing 31

Service kits 13

Setting up a vacuum system 25 Sintermetal vacuum fixtures 59 Sintermetal Vacuum chuck 53 Slide valve 77 Slot vacuum chuck 40, 48, 49 Slot vacuum chuck Starter Set 43 Slot vacuum chucks application 44 Stand filter 21 U U tank 12 v VAC-MAT adapter plate 35, 47 VAC-MAT modular chuck 28 VAC-MAT tool 31 Vacu-Vice 96 Vacuum Base 94 Vacuum chuck adapter 30 Vacuum chucks 22 Vacuum clamping systems 3 Vacuum conversion table 104 Vacuum cube 103 Vacuum electro-magnetic valve 78 Vacuum gauge 74 Vacuum grease 74 Vacuum pump 10 Vacuum supply 6 Vacuum Switch 73 Vacuum Tables 104 Vacuum tank 13 Vacuum unit 12, 18 Vilmill 61, 62 W Weiguss 92 Wire spiral hose 83 Wire spiral hose HD 83 Witte Compact Systems 19 Witte METAPOR material 87, 88 Witte VAC-MAT 26, 30 Witte Weiguss 92 γ Y distributor 75

### Information:

Weights mentioned in the catalogue are non-committal and approximate, and can deviate considerably i.e. through technical changes.

- We reserve the right to make technical changes.
- Where differences between photos and parts lists exist, the parts lists are decisive.
- Due to fluctuations of copper content in aluminum alloy colour deviations may occur during anodizing.

All details on our products in this catalogue, especially illustrations, drawings, dimensions and statements on performance are to be regarded as approximate average values. We reserve the right to change design, technical data, dimensions and weights.

The indicated standards, similar technical regulations as well as technical details, descriptions and illustrations are valid at time of printing. Our general trading conditions are valid. Our quotations are decisive.





#### Germany

#### Witte Barskamp GmbH & Co. KG

Horndorfer Weg 26-28 D-21354 Bleckede, Germany Tel.: +49(0)5854/89-0 Fax: +49(0)5854/89-40

E-mail: info@witte-barskamp.de www.witte-barskamp.de

#### Asia

#### Witte Far East Pte. Ltd.

20 Boon Lay Way, # 01 - 170 Singapore 609967, Singapore Tel.: +65-6248 5961 Fax: +65-6898 4542

E-mail: info@witteasia.com www.witteasia.com

#### USA & Canada Witte LP

2220 Northmont Pkwy, Suite 250 Duluth, Georgia 30096, USA Phone: +1 (770) 982 99 32 Fax: +1 (770) 982 99 28

E-mail: info@witteamerica.com www.witteamerica.com

#### Mexico Witte de Mexico

S.A. de C.V., c/o Linco Paseo Opera 4 Int 112-2 Lomas de Angelopolis San Andres Cholula, Puebla 72830, Mexico Phone: +52 222893-8211

E-mail: alufix@linco.com.mx www.wittemexico.com



